


# EXHIBIT A

Part 3 of 8

# CREEK RESTORATION

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION  
GM C E T C B E E D F O R D F A C I L I T Y , B E E D F O R D , I N D I A N A



Restoration North of Broomsage Road



# CREEK RESTORATION STATUS

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION

GM C E T C B E E D F O R D F A C I L I T Y , B E E D F O R D , I N D I A N A






Restoration east of Peerless Road





# CREEK RESTORATION

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION  
GM C E T C B E E D F O R D F A C I L I T Y , B E E D F O R D , I N D I A N A



Restoration East of Peerless Road



# CREEK EXCAVATION STATUS

RCRA CORRECTIVE ACTION/CERCLA REMOVAL ACTION  
GM C E T C B E D F O R D F A C I L I T Y B E E D F O R D I N D I A N A



Complete Area G Excavation